

DC-Switch Disconnectors

光伏直流隔离开关



			直流隔离开关 DC-Switch Disconnectors			
I th open at U _e	DC21B 4Poles in series	(DC-PV1)	面板安装--四孔安装 Panel mounting Four-hole mounting IP66 ¹⁾	单孔安装 Single hole mounting Φ 22.5mm IP66 ¹⁾	后部安装 Base mounting w. Door coupling IP66 ¹⁾	组合开关 Modular switch IP40 ¹⁾
型号 Type	电流(A) Current(A)	额定值(V) Rate(V)				
UKPD32-16	16	1000	.. E ..	.. Z(O) ..	.. VZV ..	.. SMAH1 ..
UKPD32-25	25	1000	.. E ..	.. Z(O) ..	.. VZV ..	.. SMAH1 ..
UKPD32-32	32	1000	.. E ..	.. Z(O) ..	.. VZV ..	.. SMAH1 ..

			直流隔离开关 DC-Switch Disconnectors			
I th open at U _e	DC21B 4Poles in series	(DC-PV1)	面板安装-- 四孔安装 Panel mounting Four-hole mounting IP66 ¹⁾	单孔安装 Single hole mounting Φ 22.5mm IP66 ¹⁾	后部安装 Base mounting w. Door coupling IP66 ¹⁾	塑料盒 Plastic enclosed IP66/67 ¹⁾
型号 Type	电流(A) Current(A)	额定值(V) Rate(V)				
UKPD32-16	16	1000	.. EH4 ..	.. Z(O)H1 ..	.. VZVH4 ..	.. PFLH4 ..
UKPD32-25	25	1000	.. EH4 ..	.. Z(O)H1 ..	.. VZVH4 ..	.. PFLH4 ..
UKPD32-32	32	1000	.. EH4 ..	.. Z(O)H1 ..	.. VZVH4 ..	.. PFLH4 ..





DC-Switch Disconnectors

光伏直流隔离开关

型 号 Type	2极并联 2+2-pole 2poles in series +2 poles parallel	4极 4-pole	4极跳线 输入上面、输出底部 4-polewith jumpersInput on top output bottom	4极跳线 输入和输出底部 4-pole with jumpers Input and output bottom	4极跳线 输入和输出上 4-pole with jumpersInput and output on top
UKPD32-16 UKPD32-25 UKPD32-32	.. A2+2 .. A2+2 .. A2+2	..A4(2xA2) ..A4(2xA2) ..A4(2xA2)	..A4B ..A4B ..A4B	..A4O ..A4O ..A4O	..A4U ..A4U ..A4U
接线图 Wiring diagram					
转换示例 Switching example					
型 号 Type	6极 6-pole	3 + 2极串联3极 2极并联 3+2-pole 3 poles in series +2 poles parallel	8极 8-pole	4 + 2极串联3极 2极并联 4+2-pole 3 poles in series +2 poles parallel	
UKPD32-16 UKPD32-25 UKPD32-32	... A6 ... A6 ... A6	..A3+2 ..A3+2 ..A3+2	... A8 ... A8 ... A8	..A4+2 ..A4+2 ..A4+2	
接线图 Wiring diagram					
转换示例 Switching example					

DC-Switch Disconnectors

光伏直流隔离开关

接线图 Wiring diagram	DC21B/DC-PV1 600V DC 1000V DC		两极串联 Poles in series	数字数量 Number of strings	型号 Type	件数 Pack pcs	重量 Weight kg/pcs
	16A	10A	2	1	UKPD32-16 A2	1	0.20
	25A	11.5A	2	1	UKPD32-25 A2	1	0.20
	32A	13A	2	1	UKPD32-32 A2	1	0.20
	29A	10A	2	1	UKPD32-16 A2+2	1	0.25
	36A	11.5A	2	1	UKPD32-25 A2+2	1	0.25
	55A	13A	2	1	UKPD32-32 A2+2	1	0.25
	16A	10A	2	2	UKPD32-16 A4	1	0.23
	25A	11.5A	2	2	UKPD32-25 A4	1	0.23
	32A	13A	2	2	UKPD32-32 A4	1	0.23
	16A	16A	4	1	UKPD32-16 A4B	1	0.24
	25A	25A	4	1	UKPD32-25 A4B	1	0.24
	32A	32A	4	1	UKPD32-32 A4B	1	0.24
	16A	16A	4	1	UKPD32-16 A4O	1	0.24
	25A	25A	4	1	UKPD32-25 A4O	1	0.24
	32A	32A	4	1	UKPD32-32 A4O	1	0.24
	16A	16A	4	1	UKPD32-16 A4U	1	0.24
	25A	25A	4	1	UKPD32-25 A4U	1	0.24
	32A	32A	4	1	UKPD32-32 A4U	1	0.24
	16A	10A	2	3	UKPD32-16 A6	1	0.36
	25A	11.5A	2	3	UKPD32-25 A6	1	0.36
	32A	13A	2	3	UKPD32-32 A6	1	0.36
	16A	10A	2	4	UKPD32-16 A8	1	0.41
	25A	11.5A	2	4	UKPD32-25 A8	1	0.41
	32A	13A	2	4	UKPD32-32 A8	1	0.41
	29A	29A	4	1	UKPD32-16 A4+2	1	0.46
	45A	45A	4	1	UKPD32-25 A4+2	1	0.46
	58A	58A	4	1	UKPD32-32 A4+2	1	0.46